PRINTED: 07/11/2012 Division of Health Care Facilities FORM APPROVED STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION (X2) MULTIPLE CONSTRUCTION IDENTIFICATION NUMBER: (X3) DATE SURVEY COMPLETED A. BUILDING 01 - MAIN BUILDING 01 -TN1912 B. WING NAME OF PROVIDER OR SUPPLIER 07/09/2012 STREET ADDRESS, CITY, STATE, ZIP CODE IMPERIAL GARDENS HEALTH AND REHABILIT 306 WIDUE WEST AVE MADISON, TN 37115 (X4) ID SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION PREFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX (X5) COMPLETE REGULATORY OR LSC IDENTIFYING INFORMATION) (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE TAG TAG DATE DEFICIENCY) N 832 1200-8-6-.08 (2) Building Standards N 832 3. All staff (nursing, dictary, maintenance, Housekeeping, therapy, social services. (2) After the applicant has submitted an application and licensure fees, the applicant must Activities, and administration) were inserviced by the Nurse Educator submit the building construction plans to the 7/10/12 - 8/3/12 on the use of power strips. department. All new facilities shall conform to the 2006 edition of the International Building Gode, 4. The maintenance employees except for Chapter 11 pertaining to accessibility will do an audit of 25 rooms and and except for Chapter 27 pertaining to electrical 5 office/common areas for proper requirements; the 2005 edition of the Use of power stips weekly x International Mechanical Code; the 2006 edition 4 weeks, then monthly x 2 months of the International Plumbing Code; the 2006 and/or until 100% compliance. The results will be reported by the edition of the International Fuel and Gas Code; the 2006 edition of the National Fire Protection Maintenance supervisor to the Quality Assurance Performance Code (NFPA) NFPA 1 including Annex A which Improvement Committee comprised incorporates the 2006 edition of the Life Safety of Medical Director, Administrator, Code; the 2010 Guldelines for Design and Director of Nursing, Assistant Construction of Health Care Facilities; the 2005 Director of Nursing, Minimum Data edition of the National Electrical Code; and the Set Coordinator, Dietary Manager, 2005 edition of the U.S. Public Health Service Activities, Social Services, Food Code as adopted by the Board for Licensing Maintenance Supervisor, and Health Care Facilities. The requirements of the Environmental Director, 2004 Americans with Disabilities Act (A.D.A.), N832 and the 1999 edition of North Carolina Handicap Accessibility Codes with 2004 amendments apply I. The trush (old mattresses, to all new facilities and to all existing facilities that pailets, various wood, etc) piled are enlarged or substantially altered or repaired next to dumpster was removed after July 1, 2006. When referring to height, area by maintenance staff on 7/9/12. or construction type, the International Building The damage ceiling tile in Code shall prevail. Where there are conflicts corridor by 200 hall nurses between requirements in local codes, the above station was replaced by listed codes and regulations and provisions of maintenance staff on 7/10/12. this chapter, the most stringent requirements shall apply. The damage celling tile in corridor next to stairway door on first floor was replaced by maintenance staff on 7/10/12. The dumaged coiling tile in This Rule is not met as evidenced by: the dining room next to the Based on observations, it was determined the sink was replaced by

Division of Health Care Facilities

LABORATORY DIRECTOR'S OR PROVIDER/SUPP ER REPRESENTATIVE'S SIGNATURE

maintenance staff on 7/10/12.

(X5).DATE h Z.

WUHC2

PRINTED: 07/11/2012

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/GLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01		FORM APPRO	
		TN1912		B. WING			
NAME OF PROVIDER OR SUPPLIER STREET A			STREET ADD	DDRESS, CITY, STATE, ZIP CODE		07/09/2012	
	L GARDENS HEALT	_ 1	MADISON,	EWESTA	VF		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRE (EACH CORRECTIVE ACTION SH GROSS-REFERENCED TO THE APP DEFICIENCY	DUMBER OF THE	
5 OF	of the residents. The findings include 1. Observation on 7 tash (old mattresse piled next to dumps) 2. Observation on 7 damaged ceiling tile a. Adjacent to fire dayses, station 5. In corridor next to in dining room next to in din dining room next to in dining room next to in dining room next	ntain the overall nursing the safety and we have the safety and we had: 7/9/12 at 12:06 PM rest, pallets, various we her. 7/9/12 at 12:07 PM rest in the following location in corridor by 200 astainway door on first to sink ance to outpatient refull 131 where the domask consists of the safety o	vealed ations: I hall st floor hab room vealed a or knob	N 832	The damaged ceiling tile in corridor at the entrance to outpatient rehab room was replaced by maintenance staff on 7/10/12. The hole in the wall in room 131 where the door knob hit the wall was repaired by maintenance staff on 7/10/12. 2. 100% audit of ceiling tiles and walls behind doors was done by maintenance staff 7/11/12 - 8/3/12. 3. The maintenance staff were inserviced by the Administrator on roplacement of damaged ceiling tiles, ropair of holes in the walls, and keeping trash picked up from around the dumpsters on 7/12/12. 4. The maintenance staff will audit the ceiling tiles and walls of 25 room and 5 offices/common areas weekly x 4 weeks, then monthly x 2 months and/or until 100% compliance. The maintenance staff will audit the dumpster area for trash bi-weekly 4 weeks, then weekly for 2 months And/or 100% compliance. The results will be reported by the Maintenance wi	nts	DATI
			-		Supervisor to the Quality Assurance Performance Improveme Committee comprised of Medical Director, Administrator, Director a Nursing, Assistant Director of Nurs Minimum Data Set Coordinator, Di Manager, Activities, Social Services Maintenance Supervisor, and Environmental Director.	f ing,	